

ST TFT-401 3192-207 Instruction Sheet


Warning! This tool should not be used on live electrical circuits. It is not protected against electrical shock! Always use OSHA/ANSI/CE or other industry approved eye protection when using tools. This tool is not to be used for purposes other than intended. Read carefully and understand instructions before using this tool.



The ST TFT-401 tool is designed to remove 10mm of jacketing from Times Microwave TFT-401 cable.

1. Open tool and place end of cable up to strip stop.

2. Rotate tool 2-3 turns.



3. Grasp tool firmly with fore-finger and thumb and pull tool to remove jacket material. If the tool does not remove the jacket section, the jacket is scored deep enough to remove it by hand.

